

Pictures of Flood Sites in August 2003, Showing Improvements (taken on 12 October 2003)



Breached section of embankment near Vehowa culvert-1



Breached section of embankment near Vehowa culvert-2



Breached section of embankment near Vehowa culvert-3



Breached section of embankment near Vehowa culvert-4,
(canal lining was also damaged)



Rod Kohi embankment and retained water (near RD595)



Land cultivated after flood water disappeared.



Bridge in Sokkar that caused erosion of protection bund



Eroded section of the protection bund of Sokkar



Bughlani superpassage next to Sokkar



Bughlani superpassage: leveled sill due to siltation



Breached road due to floods (at RD804)



Land cultivated after flood water disappeared