

Environmental Monitoring Report

Semi Annual Report

July 2019

Loan/Grant Number: L2808/G0270/G0271

Project Number: 41155-013

NEP: Electricity Transmission Expansion and Supply Improvement Project (Jan-Jun 2019) Part C, Annex 16

Prepared by the Government of Nepal for the Asian Development Bank.

This Environmental Monitoring Report is a document of the borrower. The views expressed herein do not necessarily represent those of ADB's Board of Directors, Management, or staff, and may be preliminary in nature. Your attention is directed to the "terms of use" section of this website. In preparing any country program or strategy, financing any project, or by making any designation of or reference to a particular territory or geographic area in this document, the Asian Development Bank does not intend to make any judgments as to the legal or other status of any territory or area.

Annex- 1 Photographs



Photo 1: Hoarding board installation, Khadichaur



Photo 2: Temporary labor camp at TL section



Photo 3: Local consultative meeting in Balephi RM-7



Photo 4: Local consultative meeting in Balephi RM-8



Photo 5: GRC formation meeting, Irkhu



Photo 6: GRC formation meeting, Thulo Sirubari



Photo 7: Orientation for enumerators for RP updating



Photo 8: ADB ETESIP review mission field visit



Photo 9: ADB Env. Compliance monitoring visit



Photo 10: ADB Env. Compliance monitoring visit



Photo 11: Construction of tower foundation (AP 33/0)



Photo 12: Temporary toilet for labor at TL section