



Environmental Monitoring Report

Project Number: 43253-025
February 2020
Part B: Appendices

Period: July 2019 – December 2019

IND: Karnataka Integrated Urban Water Management Investment Program - Tranche 1

Submitted by


Karnataka Urban Infrastructure Development & Finance Corporation (KUIDFC)

This environmental monitoring report is a document of the borrower. The views expressed herein do not necessarily represent those of ADB's Board of Directors, Management, or staff, and may be preliminary in nature.

In preparing any country program or strategy, financing any project, or by making any designation of or reference to a particular territory or geographic area in this document, the Asian Development Bank does not intend to make any judgments as to the legal or other status of any territory or area.

Asian Development Bank





Harihara Water Supply Distribution


Grievance Register

Month: DECEMBER-2019

Complaint No	Date	Complaint Raised Through	Name of Complainer and Details	Complaint Details	Action taken by contractor	Complaint Resolved Day	PHOTO	Remarks
1	02/12/2019	PHONE	Isnad, Temple Road, Bazar Mohalla, Gandhi Nagar, Harihar, Karnataka 577601	P.V.C PIPE DAMAGED	RECTIFIED	05/12/2019		
2	15/12/2019	PHONE	Shama shankar, Bida Kalyana mangala Rd, 577601, Harihar, Karnataka	P.V.C PIPE DAMAGED	RECTIFIED	15/12/2019		
3	20/12/2019	councilor, Siddesh	Temple Road, Bazar Mohalla, Gandhi Nagar, Harihar, Karnataka 577601	HOUSEKEEPING	ATTENDED	20/12/2019		
4	23/12/2019	councilor, Siddesh	Temple Road, Bazar Mohalla, Gandhi Nagar, Harihar, Karnataka 577601	HOUSEKEEPING	ATTENDED	24/12/2019		
4	26/12/2019	councilor, Siddesh	Temple Road, Bazar Mohalla, Gandhi Nagar, Harihar, Karnataka 577601	HOUSEKEEPING	ATTENDED	26/12/2019		







Byadqi Water Supply Distribution

MONTHLY REPORT ON GRIEVANCE REDDRESSAL

Name of the ULB: THC - Byadqi
 Sub Project: 24x7 - Water Supply
 Contractor: SHRIKANT EPC Ltd.

SLNo	Date	Name and address of the Complainer	Contact No	Complaint Details	Details of Action taken by Contractor/PIU/PMDCS C/ULB	Action taken Date	Remarks	Photograph of pre & post Action Taken
1)	17/12/19	Aditya Nalaw Nagar Byadqi	8105050128	Water Pipe line damage	18/12/19 Contractor	18/12/19	Done	Repaired
-	-	-	-	-	-	-	-	-
-	-	-	-	-	-	-	-	-

VIGNOSH - AS

Amr

(SAFETY ENGINEER)



RE-EE/31

[Signature]

Accident Analysis

Davanagere Water Supply Distribution

Package: 01-WS-05-ANALYSIS OF ACCIDENT

MONTH:-

S L D	DATE	NAME OF PERSON	S E X	A G E	TM R	DESIGNAT ION	COMPANY/ SUN/ CONTRACTOR	AGENC Y	TYPE OF ACCIDENT	NATURE OF INJURY	LOCATION OF INJURY	ROOT CAUSE	ACTION TAKEN
1	26/10/2019	manjunath	M	29	5	Helper	NBR Suter		First aid case	1st Injury	SPS Nagar	no hand gloves	provided hand gloves
2	26/10/2019	manjunath	M	27	11	Helper	3 men		First aid case	2nd Injury	not known	poor maintenance	have keeping done

Note:-Agency is the object or substance which is most closely associated with the accident causing the injury like machines, equipments, vehicles, hand tools, ladders, scaffolds, explosive, dust, gases, chemical, radiations, fire, water, floor, roof, animals & insects etc.

Name Sampath R.V

Person completing from _____

Location- SPS

Signature [Signature]

Date 26/10/19

Harihara Water Supply Distribution

Package:01ws04-ANALYSIS OF ACCIDENT

MONTH: December

SL NO	DATE	NAME OF PERSON	SEX	AGE	TIME	DESIGNATION	COMPANY/SUB CONTRACTOR	AGENCY	TYPE OF ACCIDENT	NATURE OF INJURY	LOCATION OF INJURY	ROOT CAUSE	ACTION TAKEN
1	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
2	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
3	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
4	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
5	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
6	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
7	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
8	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
9	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL
10	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL

NOTE: Agency is the object or substance which is most closely associated with the accident causing the injury like machines, equipments, vehicles, hand tools, ladders, scaffolds, explosive, dust gases, chemicals, radiation, fire, water, roof, animals & insects Etc

Person completing form: NIL

Name: Mohan Kumar

Location: HARIHARA

Signature:

Date: 03/01/2020

Byadgi Water Supply Distribution

ANNEXURE

Package: xxxx-ANALYSIS OF ACCIDENT

MONTH: December 2019
24/12/2019 9:45 AM

SL NO	DATE	NAME OF PERSON	SEX	AGE	TIME	LOCATION	COMPLAINT/ SUB CONTRACTOR	AGENCY	TYPE OF ACCIDENT	NATURE OF INJURY	LOCATION OF INJURY	FOOT CAUSE	ATTACHMENT

Note: Agency is the object or substance which is most closely associated with the accident causing the injury like machines, equipments, vehicles, hand tools, ladders, scaffolds, explosive, dust, gases, chemical, radiations, fire, water, floor, roof, animals & insects etc.

Name: VIGNESH - AS (Safely Engineer) Person completing from: VIGNESH - AS


Location: Byadgi

Signature: [Signature] Date: 31/12/2019

[Signature] RE-ENG [Signature] AE

HIV/AIDS AWARENESS TRAINING PROGRAMME

Davanagere Water Supply Distribution

	SUEZ PROJECTS PVT. LTD.	No.
	DAVANAGERE	Rev.000
	Training Attendance Sheet	Date: Jan' 2019 Page: 1 of 1

HIV/AIDS Awareness and Blood testing programme
 Training program: Mainstreaming Program For HIV/AIDS.
 Date: 21/1/2019 Time: 12:00 PM to 13:00 PM Conducted by: P. Pradeep Kumar VBD
 Topics Covered: Counsellor
 ICIC 21/1/2019

I ACKNOWLEDGE THAT I HAVE UNDERSTOOD THE ABOVE MENTIONED TOPICS 9449846971

S/N	NAME	COMPANY / DEPTT.	DESIGNATION	SIGNATURE
1.	Richu kumar	Suez	Carpenter	[Signature]
2.	Salvon	"	"	[Signature]
3.	Mahesh kumar	"	"	
4.	Noel Shon	"	"	[Signature]
5.	Congress	"	"	[Signature]
6.	Anond	"	"	[Signature]
7.	Nakul	"	"	[Signature]
8.	Rajesh	"	"	[Signature]
9.	Rajkumar	"	"	[Signature]
10.	Vishal Kumar	"	"	[Signature]
11.	Sandesh	"	"	[Signature]
12.	Nandlal	"	"	[Signature]
13.	Jeethon Kumar	"	"	[Signature]
14.				
15.				

Man Hours: 26 Hours

Sign of Trainer: P. Pradeep Kumar

INTEGRATED COUNSELING & TESTING CENTRE (ICTC), HIV TEST REPORT FORM

Name and address of ICTC centre :

GCSAICTC/KADU0021902917

Name : Surname _____ Middle Name _____ First Name Bisal

Gender: MTF/TG/TS Age: _____ Years PID# _____ Lab ID# _____

Date and time blood drawn : 21-11-2019 (DD/MM/YY) _____ (HH:MM)

Test Details

Specimen type used for testing : Serum / Plasma / Whole Blood

Date and time specimen tested : 21-11-2019 (DD/MM/YY) _____ (HH:MM)

Note :

- Column 2 and 3 to be filled only when HIV 1 & 2 antibody discriminatory test(s) used
- No Cell has to be left blank, indicate as NA where not applicable.

Column 1	Column 2	Column 3	Column 4
Name of HIV test kit	Reactive/Nonreactive (R/NR) for HIV-1 antibodies	Reactive/Nonreactive (R/NR) for HIV-2 antibodies	Reactive/Nonreactive (R/NR) for HIV antibodies
Test I <u>Monoclonal</u>	<u>NR</u>	<u>NR</u>	<u>NA</u>
Test II	<u>-</u>	<u>-</u>	<u>-</u>
Test III	<u>-</u>	<u>-</u>	<u>-</u>

Interpretation of the result : Tick (✓) relevant

- ☒ Specimen is negative for HIV antibodies
- ☐ Specimen is positive for HIV-1 antibodies.
- ☐ Specimen is positive for HIV antibodies (HIV 1 and HIV 2; or HIV 2 alone)
- ☐ Specimen is indeterminate for HIV antibodies. Collect fresh sample in two weeks.

Confirmation of HIV 2 sero-status at identified referral laboratory through ART centres

For Free HIV Counselling & Complaints call 1097

Name & Signature of

Laboratory Technician

Lab Technologist

ICTC

IMMC Davangere

Name & Signature of

Laboratory In-charge





Harihara Water Supply Distribution

HIV/AIDS Awareness programme photos



Davanagere Project
OHT, WTP and Labour Camp



Legend


- Proposed OHT
- Existing OHTS
- Labour Shed
- Bathi WTP
- TV Station WTP
- Kundawada WTP
- Project Boundary
- Zone Boundaries

Contractor:



SUEZ Projects Private Limited.
No.565/A 2nd Floor, Sapthagiri SSS Plaza,
Beside Income Tax Office, Near Channel Office Road,
Hadadi Road, Davanagere, Karnataka– 577005

Labour Camp



Legend

	Asphalt Road		Labour Shed (32)
	Bath Room		Septic Tank (1)
	Fence		Shoulder
	Kaccha Road		Toilet (20)
	Kitchen (4)		Water Tank (3)

Employer:



DAVANGERE CITY CORPORATION

Contractor:



SUEZ Projects Private Limited.
No.565/A 2nd Floor, Sapthagiri SSS Plaza,
Beside Income Tax Office, Near Channel Office Road,
Hadadi Road, Davanagere, Karnataka- 577005

PMU:



KARNATAKA URBAN
INFRASTRUCTURE DEVELOPMENT
AND FINANCE CORPORATION (KUIDFC)

PMDSCS:



Egis India Consulting Engineers Pvt Ltd.
City Corporation Zonal Office
Building No:1969/9 MCC"A" Block
2nd Floor Beside: Ashraya Hospital,
Shamanur Road DAVANAGERE-577002,
KARNATAKA

Map Name :- Labour Camp



Open Land

Open Land

Toilets


Labour Shed

Labour Shed


Kitchen

Kitchen


Davanagere Project
Pipeline Laid Status



Zone No	ZONE NAME	Zone No	ZONE NAME
ZONE1A	DEVRAJ ARUS BADAVANE	ZONE16	SARASWATI NAGAR
ZONE1B	DEVRAJ ARUS BADAVANE	ZONE17A	SUBRAMANYA NAGAR
ZONE2A	SM KRISHNA NAGAR	ZONE17B	SUBRAMANYA NAGAR
ZONE2B	SM KRISHNA NAGAR	ZONE18	SOG COLONY
Zone3A	YARAGUNTA	ZONE19A	BASHA NAGAR
Zone3B	YARAGUNTA	ZONE19B	MANDAKKI BHATTI(AZAD NAGAR)
ZONE4A	BASAVESHWARA NAGAR	ZONE20	SHEKRAPPA NAGAR
ZONE4B	HALE KUNDWADA	ZONE21	ANEKONDA METEKAL
ZONE4C	VINOBHA NAGAR	ZONE22	AZAD NAGAR
ZONE5	NIJALINGAPPA LAYOUT	ZONE23	SANTHE MAIDAN
ZONE6A	HOSA KUNDAWAD	ZONE24A	GANDHI CIRCLE
ZONE6B	HOSA KUNDAWAD	ZONE24B	HONDADA CIRCLE
ZONE7	SHAMNUR	ZONE24C	GANDHI CIRCLE
ZONE8	JH PATEL BADAVANE(SHAMNUR)	ZONE25	TALUKA OFFICE
ZONE9A	KV SHEETY PARK	ZONE26	MUNCIPAL PARK
ZONE9B	KV SHEETY PARK	ZONE27	K B EXTENSION
Zone10	K.V.SHETTY PARK GLSR	ZONE28A	SRINIVASA NAGAR
ZONE11A	ANJANEYA BADAVANE	ZONE28B	NITTUVALLI
ZONE11B	ANJANEYA BADAVANE	ZONE29	SHAKATI NAGAR
ZONE12	VIDYA NAGAR	ZONE30	SSM LAYOUT
ZONE13	TARALABALU EXTENSION	ZONE31	KARUR
ZONE14A	AVARAGERE	ZONE32A	SIR M VISHWESWARAIH PARK
ZONE14B	AVARAGERE	ZONE32B	SIR M VISHWESWARAIH PARK
ZONE14C	HOSA CHIKKANALLI	ZONE33	BASAPURA
ZONE15	ANJANEYA LAYOUT(ANJANEYA MILL)	ZONE34	TV STATION



Details Of Pipeline			
Pipe Dia (MM)	Length As Per Drawing (M)	Pipe Laid Length In (M)	Percentage
75	977115	563173	57.64%
110	158025	63172	39.98%
160	119697	12406	10.36%
200	16491	3435	20.83%
250	17420	669	3.84%
300	33864	4009	11.84%
350	3195	28	0.88%
400	7291	1571	21.55%
Total	1333098	648463	48.64%



Legend

Pipeline

Project Boundary

Zone Boundaries

Roads

Contractor:



SUEZ Projects Private Limited.

No.565/A 2nd Floor, Sapthagiri SSS Plaza,
Beside Income Tax Office, Near Channel Office Road,
Hadadi Road, Davanagere, Karnataka– 577005